



**50 YEARS OF
BLAST VIBRATION
MONITORING & CONTROL**

(No, this isn't my retirement speech. There's too much left to do.)

Quick Review of Historical Trends

Deep Dive into RI 8507

HISTORICAL TRENDS

Loss of Contact w/ Primary Studies

Greater Definition of Blasting Regulations Z

Shrinkage of the Control Crack

Comparison of Vibratory and Weather Response of Cracks

Computerization of Instrumentation

Increasing Analytical Ability

Improving Close-In Blasting Capability

Application of Blasting Research to Construction Vibrations

Increasing Sophistication of Explosive Technology Elect Dets



8896?

Nail pops

fdom, FFT

LOSS OF CONTACT w/ PRIMARY STUDIES

Who Has a Copy of RI 8507, 8896, or 9523 ?

Who Has Read These RI's from USBM

Summarize 10's of Millions of Dollars of Vibration Research

See OSM for complete collection

<https://www.osmre.gov/resources/blasting/ARblast.shtm>

8507 Structure Response & Damage Produced by Ground Vibrations from Surface Blasting

Siskind classic that introduces the concept of a frequency based vibration control limit;
the Z curve.

These limits are based upon the observation of cosmetic, hair sized cracks

8896 Effects of Repeated Blasting on a Wood-Frame House

Loose ends of RI 8507 are tied up in this report, which contains results of full scale fatigue tests (important for vibratory construction equipment) as well as full scale tests of in-plane shearing of concrete masonry units..

9523 Surface Mine Blasting Near Pressurized Transmission Lines

Reports response of field tests on pressurized pipelines subjected to full-scale surface coal mine blasts. Demonstrates that they can sustain very high particle velocities.

Reprints available from ISEE and OSM ARblast .

Memories of the birth of "Z" Top 10 from RI 8507




Figure B-1.—Safe levels of blasting vibration for houses using a combination of velocity and displacement.




Table 3.—Test structures and measured dynamic properties—Continued

Structure	No. of stories	Dimensions, ft		Construction				Natural frequency of structure, Hz		Damping, pct		Midwall natural frequencies, Hz
		Plan NS × EW	Overall height	Superstructure	Exterior covering	Interior covering	Foundation	N-S	E-W	N-S	E-W	
39	1	34 × 29	15	Wood frame	Masonite siding	Paneling and wallboard	Full basement	5	5	7		14
40	1½	28 × 31	18	do	Stucco	Plaster and lath	Partial basement	5	8	7	2	13.6
41	2	40 × 28	22	do	Wood siding	Gypsum and plaster	Full basement	10	8	4	2	16.6
42	1½	44 × 30	20	do	do	Paneling	do	5	7	5	4	11.9, 13.9
43	1½	28 × 46	23	do	do	do	do	8	5			18, 18
44	1		15	do	do	do	do					11, 11
45	2	55 × 44	32	Solid brick	Brick	Plaster on brick	do	9	10	3	3	
46	1½	38 × 40	21	Concrete block	Concrete block	Plaster	do	10		4		11, 11
47	1	87 × 38	15	Wood frame	Brick	Gypsum wallboard	do					12.5, 13.3
48	1½	36 × 24	22	do	Wood siding	do	do					16.7, 16.7
49	1½	41 × 35	27	do	do	Gypsum wallboard and plaster on lath	do					18.2, 18.2
50	1	48 × 180	14	do	Aluminum siding	Gypsum wallboard	Concrete slab	9		2		
51	2	50 × 43	28	Solid brick	Brick	Plaster on brick	Full basement					
52	1	37 × 24	16	Wood frame		Wood paneling	do					
53	1	24 × 35	15	do	Wood siding		Crawl space					
54	1	12 × 60	15	Metal walls	Metal	Paneling	None					
55	1½	40 × 31	23	Wood frame	Wood siding		Full basement					
56	1½	34 × 57	20	do	Wood siding		do					
57	1	40 × 24	20	Wood frame	Aluminum siding	Plaster and lath and paneling	Sandstone blocks partial basement		8		9.6	
58	1	40.4 × 31	26	Brick and masonry	Brick and masonry	Brick and gypsum wallboard	Masonry basement					
59	1	30.5 × 54		Wood frame	Wood siding	Gypsum wallboard	Continuous concrete footings					
60	2	54 × 26.5		do	Aluminum siding	do	do					
61	1	28.5 × 55.5		do	Brick and plywood	Gypsum wallboard and plaster	Concrete block					
62	2	34.5 × 48		do	Board and bat	Gypsum wallboard	Slab on grade	11	5	3	8	
63	2	76.8 × 80		do	Wood siding	Plaster	Wooden piers on spread footings					
64	2	34.5 × 48		do	Board and bat	Gypsum wallboard	Slab on grade					
65	1	26 × 25		do	Aluminum siding	do	Continuous concrete footings	8		6		
66	1	26.5 × 34.5		do	Wooden shingles	do	do					
67	2	19.5 × 46.5		do	Wood siding	Wood paneling except kitchen ceilings	Concrete block	8		6		
68	1	55 × 34		do	Board and bat	Gypsum wallboard	do					
69	1	41 × 37.5		do	Aluminum siding	do	do					
70	1	33 × 44.5		do	Wood panels	do	Continuous concrete footings					
71	1	23.5 × 23.5		do	Board and bat	Unfinished	do					
72	2	41.5 × 28.5		do	do	Wallboard paneling	do					
73	1	30.5 × 26.5		do	Asphalt shingles	Plaster	Concrete					
74	1	28 × 45		do	do	Wallboard	Slab and concrete block	7	7	6	9	
75	1	36.5 × 34		do	Plywood	Gypsum wallboard	Concrete					
76	1	38.5 × 40.5		do	Wood plank	Wallboard	do					

10) Of the 76 homes inspected many were distressed: and subjected a total of 240 blasts

Repainted
4-12-78
After shot



**Structure 51 -
plaster and lath walls
Over abandoned coal mine
wall paper stripped to
expose extensive cracking**




Figure 29.—Vibration gages mounted in corners and on walls for measuring structure response in structure 51.

Figure 9-4
Bureau of I



Figure 27.—Test structure 51, near a coal mine.

Structure 20



Figure 16.—Test structure 20, near a coal mine.

9) Homes included a wide variety of construction types gypsum drywall lowest PPV to induce cracking ~0.79 ips




Structure 27
Lowest PPV - 0.72 ips
to produce
cosmetic cracking in
plaster and lath



Figure 21.—Test structure 27, near a coal mine.




Example foundation support




**Structure 19 Plaster and Lath
Cracking: PPV-Fdom plots along
Line of constant displacement
on the Z curve**




Figure 15.—Test structure 19, near a coal mine.



East wall



West wall



North wall



South wall

Shots 173, 174, and 175 caused cracking, but 167 did not. Observed walls in the southwest bedroom were stripped of all wall covering and inspected carefully before and after each blast. With respect to the crack pattern in Figure 9-4, inspection after shot 173 showed

$$PPV = 25.6 \text{ mm/s} \sim 1.05 \text{ ips}$$

Nothing very significant. Test area A's few cracks (in Figure 9-4) are more evident. A few extensions and connections in area B. One new crack in B.

After shot 173 the right-half side of north wall was painted and cracks large enough to show through paint were marked. After shot 174 the inspection showed

$$PPV = 47.2 \text{ mm/s} \sim 1.85 \text{ ips}$$

New cracks in area A and preexisting ones more evident. Nothing new in other areas.

After shot 175 the inspection revealed

$$PPV = 216.9 \text{ mm/s} \sim 8.53 \text{ ips}$$

“major” cracking in north and south walls—“major” diagonal crack through new paint on north wall, connecting hairline cracks existing previously, and widening considerably. Crack over door is quite wide. Previous condition not known. Very light horizontal crack near door. Nothing significant on east wall. New and wider cracks on south wall near window. Horizontal cracks between windows. Crack below window on west wall. Quite evident crack widths measured. Cement block addition developed a vertical crack through three blocks lower northeast corner east wall through mortar and block.

8) Interior wall coverings were inspected immediately before and after each blast

7) Home velocity response was amplified
(eg was greater than peak particle ground velocity)





Figure 39.—Amplification factors for blast-produced structure vibration (corners), all homes.

TABLE 12-2 Cracking Observed from Blasting

Shot	Ground Vibration Level		Crack Observation	
	V	H ₁ (East-West)		H ₂ (North-South)
45	0.38	1.03	0.54	Crack in cement block mortar joint ^a
82	2.21	1.41	1.75	Crack in joint compound over nailhead
83	3.05	2.75	1.64	Corner crack extension
84	2.17	2.01	1.44	Crack in joint compound over nailhead
86	0.85	1.34	1.15	Two-corner crack extensions
89	0.40	0.88	0.78	Corner crack extension
97	1.17	1.11	1.81	Crack in joint compound over nailhead
101	3.12	3.52	2.19	Corner crack extension
102	4.77	3.21	4.25	Plywood subfloor crack ^b
114	3.33	3.43	NA ^c	Brick veneer mortar joint crack
115	6.19	6.22	3.52	Basement block mortar joint cracks
126	6.19	6.94	5.27	Chimney mortar crack, all sides; basement block mortar joint separation (minor damage at RI 8507)


^a Same position as crack after shot 115; up to shot 115, crack was difficult to distinguish from shrinkage crack. Block wall was unreinforced.

^b Subfloor only; test house not completed with underlayment or finish floor.


^c NA, not available.

Source: Stagg et al. (1984).

6) Observations of blast -induced cracking were based on threshold of cosmetic cracking lower than previous



5) 0.72 ips -- lowest single axis, peak particle velocity associated with blast induced cosmetic cracking observed by USBM personnel.



Structures 19, 27, 51
Plaster & Lath, Old, Distressed
Old in the late 1970's
Lowest PPV = 0.72 ips (18.2 mm/s)
Threshold Crack

Structure 20
Newer, Gypsum Wallboard
Lowest PPV = 0.79 ips (20 mm/s)
Threshold Crack



United States Department of the Interior

BUREAU OF MINES

TWIN CITIES RESEARCH CENTER
5629 MINNEHAHA AVENUE SOUTH
MINNEAPOLIS, MINNESOTA 55417

March 4, 1981

Memorandum

To: Donald E. Raiston, Chief, Branch of Technology Transfer, Division of Minerals Health and Safety Technology
Through: Donald G. Rogich, Director, Division of Research Center Operations, Washington, D.C.
David R. Forshey, Director, Division of Minerals Environmental Technology, Washington, D.C.
John W. Corwine, Research Director, TCRC
Dennis V. D'Andrea, Research Supervisor, Blasting Technology and In Situ Mining, TCRC
From: David E. Siskind, Group Supervisor, Blasting Technology, TCRC
Subject: Approval Request for Open Filing of "Supplimentary Information for Bureau of Mines Study on Response and Damage Produced by Ground Vibrations from Blasting, RI 8507"

Table with columns: SISKIND GROUP, THRESHOLD, DATA POINTS (F, D, V, A), STRUCTURE #, NEW B.M. DATA. Lists various Siskind groups and their associated data points.

Unpublished Siskind document in Dowding files identifies points at the constant displacement line in the Z curve

A presentation was made of the Bureau of Mines research reported in RI 8507 at a meeting of the United States Geological Survey in Washington, D.C. on March 2, 1981. The meeting was held to discuss the results of the raw data used for the analyses and also some additional plots. Dr. Lindsey Norman was in attendance and suggested that this material be made available through NTIS.

As a result, the subject draft OFR has been prepared. In addition to the two above items, the report contains the 55 most significant review comments made about RI 8507, replies to these comments, and an errata sheet.

I request that this report be placed on open file at the major Bureau of Mines Centers and libraries and also made available through NTIS.

Enclosed are four copies of the report.


Signature of David E. Siskind
DAVID E. SISKIND

Table with columns: SISKIND GROUP, NONDAMAGE, DATA POINTS (F, D, V, A), STRUCTURE #, ADDITIONAL B.M. DATA. Lists various Siskind groups and their associated data points.

Enclosures

cc: D. D'Andrea
R. Dick
C. Dowding

Now available on iti.northwestern.edu/acm



4) Probability of blast induced cosmetic cracking is zero below 0.5 ips



Figure 59.—Probability damage analysis summary, set 7.

TABLE 6. - Comparison of strain levels induced by daily environmental changes, household activities, and blasting

Loading phenomena	Site ¹	Induced strain, $\mu\text{in/in}$	Corresponding blast vibration level, ² in/s
Daily environmental changes.	K_1	149	1.2
	K_2	385	3.0
Household activities:			
Walking.....	S_2	9.1	.03
Heel drop.....	S_2	20.0	.03
Jumping.....	S_2	37.3	.28
Door slam.....	S_1	48.8	.50
Pounding a nail....	S_{12}	88.7	.88

¹From figure 13.

²Based on envelope line of strain versus ground vibration plot.



DOT block grant allowed accumulation of crack measurement in some 20 (now ~ 30) different homes


Micro-Meter Crack Response Book

[Additional Case Studies](#)

[Expanded Grand Summary Table](#)

[New Appendices](#)

[ISEE](#)



Typical crack response to changes in temperature and humidity are many times greater than at vibration levels that are annoying to humans

2) Dominant frequency for development of the Z curve was based upon data presented in Figure 54 and Figure 10-2 in CV




TABLE 10-1 Frequency Characteristics of Case Histories Involving Cosmetic Cracking

Case	f_{peak} (Hz)	f_{-70} (Hz)	f_{+70} (Hz)	PPV (mm/s)	Shot	Observation	Chapt. 9 Case ^c	Environment
1	20	7	40	124 R	13	Crack	1	Test
2	30	13	40	24 T	173	Crack	2	Mining
3 ^d	20	18	22	24 T	167	No crack	2	Mining
4 ^d	14	12	17	20	10	Crack	3	Mining
5	12	11	15	11	12	No crack	3	Mining
6	5	3	11	185	9	Crack	4	Mining
7	7	5	8	136	8	No crack	4	Mining
8	35	8	40	302	2	Crack	5	Construction
9	22	20	55	51	2	Crack	6	Construction
10	5	3.5	30	12	—	No crack	Unpubl.	Mining

^a f_{peak} , frequency at the maximum amplitude.

^b f_{-70} , frequency at 70% of the maximum amplitude.



^c Case-number from Chapter 9

^d Plotted in Figure 10-2;
R = radial, T = transverse.

3 = structure 51
4 = structure 20

1) To extend 8507 experience beyond residential structures measurement of velocity time histories can be supplemented with calculation of response spectra and strain from measured structure velocity response

Urban Structures Unresponsive Compared to Houses even when excited by larger blasting vibrations because of their mass and the ultra high frequency excitation pulses




Timing, frequency and amplitudes of motions at various locations around **urban** structure show low, de-amplified response compared to the amplified response of small residential (**house**) structures even though urban excitation


**RI 8896 Test House
companion document to 8507**




**Addresses cracking
from multiple events and
of stronger materials
first use of micrometer
crack response**



Instrumentation difficult at dawn of digital age



Measurement of micro-meter deformation at stress risers



Lower level of threshold of cosmetic cracking plaster popping over nail heads

10-20-89
SHOT 97 (1)

5) Micro-inch response of cracks to weather and occupant activity are larger than typical blast excitation




FIGURE 20. - LVDT.






FIGURE 19. - Kaman displacement system (top) and 124-mm strain gauge.

TABLE 6. - Comparison of strain levels induced by daily environmental changes, household activities, and blasting

Loading phenomena	Site ¹	Induced strain, $\mu\text{in/in}$	Corresponding blast vibration level, ² in/s
Daily environmental changes.	K_1	149	1.2
	K_2	385	3.0
Household activities:			
Walking.....	S_2	9.1	.03
Heel drop.....	S_2	20.0	.03
Jumping.....	S_2	37.3	.28
Door slam.....	S_1	48.8	.50
Pounding a nail....	S_{12}	88.7	.88

¹From figure 13.

²Based on envelope line of strain versus ground vibration plot.




Micro-Meter Crack Response Book

[Additional Case Studies](#)

[Expanded Grand Summary Table](#)

[New Appendices](#)

[ISEE](#)



A close-up photograph of a person's hand pointing to a vertical crack in a wall. The wall is composed of red bricks on the left and grey concrete masonry units (CMU) on the right. The crack runs vertically through the mortar joint between the brick and the CMU. In the background, a silver pickup truck and a brown van are parked outdoors under a clear blue sky.

4) Brick work and concrete masonry unit (CMU) walls are less susceptible to cosmetic cracking from blasting than drywall

TABLE 12-2 Cracking Observed from Blasting
Ground Vibration Level

3) Thus engineered structures are stronger


Shot	Ground Vibration Level		Crack Observation	
	V	H ₁ (East-West)		H ₂ (North-South)
45	0.38	1.03	0.54	Crack in cement block mortar joint ^a
82	2.21	1.41	1.75	Crack in joint compound over nailhead
83	3.05	2.75	1.64	Corner crack extension
84	2.17	2.01	1.44	Crack in joint compound over nailhead
86	0.85	1.34	1.15	Two-corner crack extensions
89	0.40	0.88	0.78	Corner crack extension
97	1.17	1.11	1.81	Crack in joint compound over nailhead
101	3.12	3.52	2.19	Corner crack extension
102	4.77	3.21	4.25	Plywood subfloor crack ^b
114	3.33	3.43	NA ^c	Brick veneer mortar joint crack
115	6.19	6.22	3.52	Basement block mortar joint cracks
126	6.19	6.94	5.27	Chimney mortar crack, all sides; basement block mortar joint separation (minor damage at RI 8507)

^a Same position as crack after shot 115; up to shot 115, crack was difficult to distinguish from shrinkage crack. Block wall was unreinforced.

^b Subfloor only; test house not completed with underlayment or finish floor.

^c NA, not available.

Source: Stagg et al. (1984).



2) NBS tests confirm the high strain resistance of CMU walls




FIGURE A-11. - In-place 5- by 5-ft masonry block wall at NBS Tridirectional Test Facility.

Deep dive into low frequency excitation leads to Discussion of the meaning of CMU response to cyclic shearing



United States Department of the Interior

BUREAU OF MINES
Twin Cities Research Center
5629 Minnehaha Avenue South
Minneapolis, MN 55417-3099



November 9, 1993

Ken Eltschlager
OSMRE
Ten Parkway Center
Pittsburgh, PA 15220

Dear Ken:

Along with Willard Pierce and Mark Stagg, I have reviewed the latest version of Vince Chiarito's report, dated Sept. 1993. The report appears to have some major inconsistencies. I also have a serious problem with paragraph 93 in the conclusions which states that mortar joint cracks are expected in the impacted communities (P.95). The analysis upon which this is based is a misinterpretation of Stagg's data on masonry strain, cracking, and associated vibration amplitudes. I also believe your worst case vibration amplitude scenario is being carelessly applied and the numbers themselves may be unrealistic.

Concerning the strains, there are two problems: 1) strains associated with cracking and identification of whether they are global or local strains and 2) vibration amplitudes associated with specific strains.

STRAINS: GLOBAL VERSUS LOCAL:

Chiarito uses selected strain values from Stagg's figures 35-37 (RI 8896) in his figures 2.22 and 4.22 and associated them with both threshold cracking and specific vibration amplitudes. In discussion with Stagg, he regrets labeling these "strains" when some are actually displacements between already-separated block segments. The coarse texture in the mortar made hairline joints difficult to see and, more importantly, it was impossible to differentiate between drying surface cracks in the mortar and true separations. Only in the wall section tests with NBS was it possible to constantly monitor load and accurately determine global strains at failure. The general frustration of trying to differentiate between structural and non-structural hairline cracks led to Stagg adopting a crack-width criteria with corresponding local strains of $770\text{-}7700\mu\epsilon$ (P.50). All Stagg's strain values for the test house are local strains.

From Stagg's and Woodward's reports, I offer the following 5 items concerning strains and cracking from the NBS tests:

1. Load-controlled test at NBS showed an inflection point at about .013-in wall displacement, or $100\mu\epsilon$, suggesting the beginning of



DEPARTMENT OF THE ARMY
WATERWAYS EXPERIMENT STATION, CORPS OF ENGINEERS
399 HALLS FERRY ROAD
VICKSBURG, MISSISSIPPI 39180-4150

REPLY TO
ATTENTION OF

December 16, 1993

Structural Mechanics Division
Structures Laboratory

Dr. David Siskind
U.S. Department of the Interior
Bureau of Mines
Twin Cities Research Center
5629 Minnehaha Avenue South
Minneapolis, Minnesota 55417-3099

Dear Dr. Siskind:

We have reviewed your comments on the latest version of "Experimental and Analytical Studies of the Vibration Response of Residential Structures Due to Surface Mine Blasting." Our response and clarifications are:

The conclusion "Using the maximum peak ground velocity prediction by Eltschlager and Michael (1993) at 0.39 in./sec and above, cracking is expected in block or brick veneer joints." will change to "...cracking could occur..." The worst case scenario is applied in an objective manner as is the rest of the data. The only misinterpretation that exists is apparently in the presentation and description of some strain data and tests from Stagg (RI 8896).

STRAINS: GLOBAL VERSUS LOCAL

Two terms are used for strain: "global" and "local." These terms, "global" and "local" are vague and do not have any specific significance with respect to describing the strain at any particular point. The correct terminology for engineering strain as used in the report is defined by a change of length over the original gage length. Engineering strain is used to determine if cracking has occurred. We infer that cracking occurs when strain values exceed the tensile capacity of the material at a point. This means that "cracking" may occur without a crack width being sufficiently wide to be observed visually.

Since Stagg (RI 8896) labeled his data as strain, we interpreted the data as strain. We recognize that any gage providing an average strain over the gage length, and that includes the data presented in Figures 2.22 and 4.22, needs further explanation of the strain reported. We will explain that the strains taken from figures in RI 8896 are engineering



United States Department of the Interior

BUREAU OF MINES
Twin Cities Research Center
5629 Minnehaha Avenue South
Minneapolis, MN 55417-3099



January 3, 1994

Mr. Peter Michael
OSMRE, ESC
Ten Parkway Center
Pittsburgh, PA 15220

Dear Peter:

I am writing to you as a follow-up to our conference call with the Corps, December 28, enumerating our key concerns and related technical issues.


The Corps is determined to assess damage potential based on their analysis of our data (from RI 8896) although we described how our own interpretation of that data has changed since we wrote that report in 1983. I think the end result is going to be a conclusion which is unrealistic and will likely be challenged.

There is nothing wrong with doing a worst-case scenario. However, every component in that scenario must be a worst plausible assessment. Stringing together a series of unlikely events (with some clearly in error as in the case of Stagg's "strain" values) can give an absurd conclusion. Such an argument could be used to justify never driving a car or flying in a plane. I do not believe the changes the Corps proposed to make will be sufficient and also do believe a bad conclusion is far worse than one omitted because of a lack of data.

With this letter are our key points plus a strain/velocity work sheet. If, at some future date, you want us to look farther into the issue of masonry cracking, response of masonry, and masonry-specific safe-level criteria, we will be happy to prepare a proposal to do so. Until then, our best estimate of masonry failure threshold is still at least 2.0 in/s.

Finally, none of the issues we raised in our November 9 letter to you re: worst-case PPV estimate for Daylight/McCutchanville have been addressed. Again, OSM may be using numbers with little basis in reality.

Lateral displacement of top of 64 inch high CMU wall



Siskind Conservative interpretation
 $\Delta y = 0.013$ in \Rightarrow
"global" shear strain, λ , = $\Delta y/H =$
 $0.013/64 = 0.000200 = 200\mu\lambda$
with no visible cracking
only slight change elastic behavior

CMU could withstand global shear strain of $1000\mu\lambda$,
cycle 100,000 times
increase the load (follows same slope \Rightarrow elastic)
To reach $\sim 1300\mu\lambda$
before cyclic loading would produce a diagonal crack

Figure 7.9. Load displacement curve for test P1



One of two eccentrically weighted rotors to deform entire house

1) Repeated excitation at 0.5 ips does not induce cosmetic cracking



TABLE 12. - Cracks observed after shaker excitation

Shaker vibration equivalency ¹ and crack description	Number of cycles at cracking	
	Run	Total ²
Run 1, ~ 0.5 in/s:		
Entryway tape joint crack.....	52,000	56,000
Crack in joint compound over nailhead in master bedroom.....	52,000	56,000
Fireplace mortar joint crack extension ³	52,000	56,000
Run 2, ~ 0.5 in/s:		
Chimney trim broken loose from siding ³	>1	>108,500
Mortar joint crack at top of chimney.	>1	>108,500
Run 3, ~ 0.3 in/s:		
Brick veneer mortar joint cracks.....	15,000	229,500
4 cracks in joint compound over nailheads.....	25,000	239,000
Run 4, ~ 0.75 in/s:		
Vertical crack through brick veneer mortar.....	14,500	293,500
Cracks in joint compound over nailheads.....	60,000	339,500
Basement block mortar joint crack extensions.....	>1	>339,500
Run 5, ~ 1.0 in/s:		
Brick veneer mortar falling out.....	>1	>339,500
Basement block mortar joint crack extensions.....	>1	>339,500
Crack in wallboard.....	22,000	361,500

Drove test house at its natural frequency (~ 7 hz) at strains (response) ~ those produced by ground motions at 0.5 ips

¹Based on envelope response from plot of ground vibration versus structure motion at site A₄ (fig. 13), high corner, east wall, as structure was at resonance.

²At vibration equivalency of ~ 0.5 in/s; including cycles induced by blasting and frequency sweeps.

³Cracking suspect because superstructure was racked against normally foundation-driven fireplace.